

Submission number **2020_5086**

Case ID **2020/69/BE**

1 | Countries concerned

Countries concerned* **Lithuania Romania Bulgaria Slovenia Poland United Kingdom Belgium Czech Republic Italy Iceland Cyprus Germany Greece Portugal Sweden Finland France Malta Norway Hungary Austria Latvia Denmark The Netherlands Estonia Spain Slovakia**

2 | Producer/Distributor submitting notification

The producer/distributor* **Is not the Notifier**

Name or identification of the producer/distributor* **BRP ED Benelux**

Responsibility

Contact name* **Olivier Hermanns**

Address* **Skaldenstraat 125, Oostakker East Flander**

Town/City* **Gant**

Postal code* **9042**

Country* **Belgium**

Email* **olivier.hermanns@brp.com**

Telephone* **+32 9 218 2609**

Website

Type* **- Distributor of the product
- Importer of the product
- Manufacturer of the product**

Name or identification of the notifier* **BRP**

Responsibility
Contact name* **Marie-Claude Simard**
Address* **726 St-Joseph**
Town/City* **Valcourt**
Postal code* **J0E 2L0**
Country* **Canada**
Email* **marie-claude.simard@brp.com**
Telephone* **0114505326195**
Website*

3 | Product involved

Category* **Recreational crafts**
Sub-category
Trademark* **Sea-Doo**
Model name
Bar code
Total number of products held **3596**
Custom code
Country of origin* **Mexico**
Brief description* **Personal watercraft model year 2019 Sea-Doo GTX, RXT and Wake PROequipped with 230 and 300 engines.**
Detailed description **No file(s) attached**
Photo **No file(s) attached**

4 | Risk assessment of the notifier

Description* **The intake grate may detach from the vehicle while in use. Riding at speeds over 55 mph (88 km/h) without an intake grate may cause unpredictable vehicle behavior which could lead to occupant ejection. In some situations, this could result in serious injuries or even death.**
Record of accidents
Level of risk* **Serious**
Report document **No file(s) attached**

5 | Corrective actions already taken or planned

Action* **Corrective actions**
Please specify **Safety action**

Scope of the actions* **EU wide**
Duration of the actions* **Permanent**
Results of the actions
Company taking action **BRP**

Additional information **European distributors will be informed in February 2020. After receiving the information, BRP independent distributors are responsible to inform their own dealers network and customers. In countries in which BRP has its own dealers network, letters and bulletins will be sent to dealers and letter will be sent to registered customers. •All vehicles involved in the previous recall (2019/251/BE) are included in this new safety recall and need to have a new repair. BRP modified the required repair. Also, additional vehicles are added to this campaign. •The parts for the procedure will be available starting April 6th.**

6 | Company(ies) in the supply chain which hold affected products

Details of the COMPANY (IES) **No file(s) attached**

7 | Other

Language **No file(s) attached**