

#### REPUBLIC OF CYPRUS

# MINISTRY OF COMMUNICATIONS AND WORKS



14 May 2008

Circular No. 7/2008

TEN 5.13.09 TEN 4.2.08.1.06.7

To all Owners, Managers and Representatives of Ships under the Cyprus Flag equipped with Halon Fixed Fire Fighting Systems
C.C.: To all Recognized Classification Societies and Inspectors of Cyprus Ships

Subject: Regulation (EC) No 2037/2000 of the European Parliament and of the Council of 29 June 2000 on substances that deplete the ozone layer and its application to existing ships.

With reference to our Circulars No. 8/2004, No. 13/2004 and No.5/2005 and our letter dated 09 August 2007 relating to the subject matter, we wish to advise you that following a Port State Control (PSC) inspection last July, onboard a Cyprus flagged vessel at the port DE HUELVA, Spain, equipped with Halon fixed fire fighting / extinguishing system, in accordance with the provisions of Article 4 paragraph 4 (v) of Regulation No 2037/2000/EC (thereafter referred to as "the Regulation"), the Spanish Maritime Authorities informed us, that they do not accept our interpretation / policy on the above mentioned EC Regulation, insisting that Halon Fixed Fire Fighting System onboard, used for fire fighting - extinguishing should have been decommissioned the latest by 31 December, 2003.

The Spanish Maritime Authorities made it clear that Cyprus flagged ships or any other EU flagged ship with Halon fixed fire fighting system onboard, used for fire fighting extinguishing will not be allowed to enter Spanish ports. As a result of the above, the Department of Merchant Shipping entered into a dialogue with the European Commission in an effort to clarify the issue why the above use of Halon falls under the provisions of the Regulation.

Unfortunately, the European Commission has recently informed us that they do not accept our interpretation, insisting also, that Halon fixed fire extinguishing systems onboard used for fire fighting / extinguishing should have been decommissioned the latest by 31 December 2003. In the case of Cyprus, the latest by 1<sup>st</sup> of May 2004, the date of accession to the EU.

E-mail: maritimeadmin@dms.mcw.gov.cy, Web page http://www.shipping.gov.cy

In this respect, all ships under the Cyprus Flag equipped with Halon Fixed Fire Fighting Systems should replace it with alternative systems that do not make use of Halon, at the next scheduled dry-docking but not later than 31 December 2008.

Furthermore, we would like to remind you that the existing system (Halon based system) shall be decommissioned in accordance with the provisions of Article 16 (Recovery of used controlled substances) of the Regulation and decommissioning can only take place in approved halon banking and reception facilities. Further information on approved halon banking and reception facilities designated by the International Maritime Organization, contained in the Circular of the Sub-Committee on Fire Protection, FP.1/Circ.35, dated 7 January 2008, is attached.

Finally, the vessel's Classification Society should inform us upon replacement of the Halon system and provide us with the details of the alternative system that will be used.

The Owners, Managers and Representatives of ships under the Cyprus Flag equipped with Halon Fixed Fire Fighting Systems are advised to strictly abide by the present Circular which repeals and substitutes all Circulars issued to date with regard to the subject matter (Circular No. 8/2004, dated 19.2.2004, Circular No. 13/2004, dated 26.4.2004, Circular No. 5/2005, dated 18.3.2005 and Circular No. 5/2007 dated 21.2.2007).

### S. S. Serghiou

Director
Department of Merchant Shipping

cc: Permanent Secretary, Ministry of Communications and Works
Maritime Offices of the Department of Merchant Shipping abroad
Attorney General of the Republic
Permanent Secretary, Ministry of Foreign Affairs
Director of Environmental Service
Diplomatic and Consular Missions of the Republic
Honorary Consular Officers of the Republic
Cyprus Shipping Council
Cyprus Union of Shipowners
Cyprus Bar Association

4 ALBERT EMBANKMENT LONDON SE1 7SR

Telephone: 020 7735 7611 Fax: 020 7587 3210

Ref. T4/4.01



 $\boldsymbol{E}$ 

7 January 2008

FP.1/Circ.35

#### HALON BANKING AND RECEPTION FACILITIES

- The Sub-Committee on Fire Protection, at its fortieth session (17 to 21 July 1995), having noted that, under the 1992 amendments to the 1974 SOLAS Convention (resolution MSC.27(61)), new installations of halon fire-extinguishing systems had been prohibited as from 1 October 1994, recalled its previous decision that, for the time being and until appropriate halon banking facilities were established, halons need not be withdrawn from existing systems.
- The Sub-Committee considered it useful that information on the availability of halons at various ports of the world be circulated, as existing halon systems may need to be recharged with recycled halons to comply with the relevant requirements of the 1974 SOLAS Convention.
- In order to facilitate the dissemination of information on available halon banking facilities, Member Governments were requested (FP/Circ.1) to advise the Secretariat of any national halon banking facilities established under their jurisdiction, together with their address, telephone and fax numbers to enable contacts for the purpose of arranging the deposit of decommissioned halons or the purchase of recycled ones.
- 4 The attached annex contains the revised listing of halon banking and reception facilities based on information received by the Secretariat during 2007, which supersedes that annexed to FP.1/Circ.33 and Corr.1.
- Member Governments are requested to provide the Secretariat with information on halon banking and reception facilities, which will be included in future FP.1 circulars. Member Governments are also requested to bring the annexed information to the attention of shipowners, ship operators and other parties concerned.

\*\*\*

**ANNEX** 

## HALON BANKING AND RECEPTION FACILITIES AND OTHER RELEVANT INFORMATION

Country	Name and address	Remarks
Argentina	Instituto Nacional de Tecnologia Industrial (INTI) Av. Gral.Paz e/Albarellos y Constituyentes B1650WAB San Martin, Buenos Aires, Argentina Tel: (+54 11) 4724-6200/6300/6400 Website: www.inti.gov.ar /E-mail: cecon@inti.gov.ar Ing. Ana Maria Di Pace	Procedures:  1 Users of Halon 1301 installations should contact INTI.  2 The INTI offers advice and information on authorized operators.  3 The INTI analyses halon 1301 for withdrawal and recommends a destination for reception halon 1301.  4 Users should contact an authorized operator for the withdrawal of halon 1301.  5 In the case of conversion of the entire system, INTI provides a certificate to the user, once the original system is withdrawn.
Australia	Australian National Halon Bank c/o DASCEM 126 Trennery Crescent ABBOTSFORD VIC 3067 Australia Tel.: +61 3 9418 0552 Fax: +61 3 9473 1450 E-mail: Elvira.nigido@coffey.com.au	In view of the stock of recycled halon 1301 now held by the Australian National Halon Bank, the supply of halon to a foreign flag ship in an Australian port can be guaranteed on request. Nevertheless, such a supply will be limited to a "one off" provision essential for the safe operation of the ship.  The supply of halon from the Australian National Halon Bank will be subject to approvals from the Department of the Environmental and Heritage and the Australian Maritime Safety Authority. The Australian national Halon Bank will acquire these approvals on behalf of the foreign flag ship prior to supply.  The Australian National Halon Bank is committed to ensuring that a supply of recycled halon 1301 over and above that required for Australia's domestic needs will be retained for the purpose of meeting the emergency needs of foreign flag ships.  Recycled halon of the Australian National Halon Bank will meet the requirements of ASTM D5632 as adopted by the U.S. Department of Defense.  The Australian National Halon Bank can also safely dispose of contaminated halon, or halon removed from decommissioned fire protection systems.

Country	Name and address	Remarks
Brazil	Sollax Equipamentos de Segurança Rua Vieira Do Couto 286 Rocha Miranda CEP 21545-130 Rio de Janeiro Brazil Tel: +55 21 372 8920 Fax: +55 21 372 8791	Halon types: 1211 and 1301 (recycled) Adopted procedures: ISO 7002 requirements Ability: receiving, supply and recharging on request
	Enchente Sistemas Contra Incendio Rua Ozeia Mota 233 Higienopolis CEP 21061-050 Rio de Janeiro Brazil Tel: +55 21 280 2749 Fax: +55 21 280 9294	Halon types: 1211 and 1301 (recycled) Adopted procedures: ISO 7002 requirements Ability: receiving, supply and recharging on request
Canada	Canadian Halon Banking Clearing House and Information Centre:  Tel: +1 800 463 6852; Ext. 279 (English) Ext. 261 (English/French)  Canadian Standards Development and Certification Organization Underwriters' Laboratories of Canada (ULC) 7 Crouse Road Scarborough, Ontario Canada, M1R 3A9 Tel: +1 416 757 3611 Fax: +1 416 757 3948	Underwriters' Laboratories of Canada (ULC) has been accredited by the Standards Council of Canada to develop and implement National Standards on Fire Protection. The ULC Halon Bank offers clearing house services and puts clients, including international merchant ships in Canada, in touch with appropriate certified companies listed in the following pages.

Country	Name and address	Remarks
Canada (continued)	The following companies provide full servicing of Halon 1301 systems (Certification category I):  Control fire systems Ltd. 63 Advance Road, Building "A" Toronto, Ontario Canada, M8Z 2S6 Tel: +1 416 236 2371 Fax +1 416 233 6814  Superior safety Inc. 989 Century Street Winnipeg, Manitoba Canada, R3H 0W4 Tel: +1 204 694 0140 Fax: +1 204 694 1590	<ul> <li>Charging, recharging and hydro-testing of halon system containers;</li> <li>repair and maintenance of all system components;</li> <li>determination of quality of halon 1301;</li> <li>reconditioning of recovered halon to acceptably quality requirements;</li> <li>dismantling of systems; and</li> <li>field inspections, including certification of the integrity of installed systems.</li> </ul>
	The following companies provide limited servicing of Halon 1301 systems:  CASP Aerospace Inc. Pointe-Claire, Quebec Tel: +1 514 630 7777 (A, B only)  CFH Securité Inc. Lachine, Quebec Tel: +1 514 639 0339  Classic Fire Protection Inc. North York, Ontario Tel: +1 416 740 3000	<ul> <li>Services provided (Certification category II):</li> <li>charging, recharging and hydro-testing of halon system containers;</li> <li>repair and maintenance of all system components;</li> <li>dismantling of systems; and</li> <li>field inspections, including certification of the integrity of installed systems.</li> </ul>

Country	Name and address	Remarks
Canada (continued)	D & L Engineering Sales Ltd. Halifax, Nova Scotia Tel: +1 902 429 3790	
	Douglas Fire Safety Systems Inc. Ottawa, Ontario Tel: +1 613 733 5348	
	Equipment Globe Inc. Globe Fire Equipment Inc. Lachine, Quebec Tel: +1 514 631 2534	
	Extincteurs prud'homme Maple Grove, Quebec Tel: +1 514 225 7637	
	Levitt-Safety Ltd. Oakville, Ontario Tel: +1 905 829 3299	
	Magna Fire Protection & Security Ltd. Brampton, Ontario Tel: +1 905 791 9606	
	Sentry Fire Equipment Ltd. Sarnia, Ontario Tel: +1 519 383 6060	
	Superior Safety Inc. Thunder Bay, Ontario Tel: +1 807 623 2797	

Country	Name and address	Remarks
Canada (continued)	Name and address  The following companies provide inspection of halon 1301 systems (Certification category III):  Acklands Ltd. Richmond Hill, Ontario Tel: +1 905 731 8975  Anderson Fire Protection Ottawa, Ontario Tel: +1 613 228 1881  Cerberus Pyrotechnics Montreal, Quebec Tel: +1 514 725 1025  Cronin Fire Equipment Ltd. Nepean, Ontario	Remarks  Field inspections, including certification of the integrity of installed systems
	Tel: +1 613 727 5330  Dunlop-Beaufort Canada Ltd. Richmond B.C. Tel: +1 604 278 3221  First Stage Fire Protection & Sec. Ltd. Downsview, Ontario Tel: +1 905 475 8641  Lyons Fire Protection Services Inc. Etobicoke, Ontario Tel: +1 416 674 5633	

Country	Name and address	Remarks
Canada (continued)	Standard Mechanical Mississauga, Ontario Tel +1 905 625 9505	
	Vipond Fire Protection Ltd. Mississauga, Ontario Tel: +1 905 564 7060	
Croatia	Antipiros d.o.o. Split 21000 Split Pujanke 77A Iirvatska Tel: +21 377 622/611 or +21 376 733/144 Fax: +21 377 622	Halon banking facilities are available as follows:  1 Halon 1301 - 1,000 kg 2 Halon 1211 - 200 kg
Denmark	Danish Halon Bank C/O Danish Institute of Fire Technology Datavej 48, DK-3460 Birkerod Denmark Tel: +45 45820099 Fax: +45 45820999	Estimated stock of halon 1301: approximately 5,000 kg Estimated stock of halon 1211: approximately 1,000 kg
Egypt	Tbrogas Products of Egypt Headquarters Cairo Arab Republic of Egypt Tel: +202 749 5035 Fax: +202 749 5003	Facilities for storage of untreated halon gas as well as direct sale of treated halon gas are available at two stations of this company.
	Portsaid Free Zone Portsaid, Egypt Tel: +066 325 397 Fax: +066 325 397	

Country	Name and address	Remarks
Finland	Federation of Finnish Insurance Companies Bulevardi 28 00120 Helsinki Finland Tel: +3 58 0 680 401 Fax: +3 58 0 647 540	The Government of Finland decided not to establish any halon banking facilities within its jurisdiction. However, Finnish insurance companies have established a data bank, which contains contact information of companies who have halon gas in their procession.  Decommissioned halons can be inquired from the Federation of Finnish Insurance Companies.
France	ABC Protection Environnement 13 rue du Compas 9142 95074 Saint-Ouen l'Aumône France Tel: +33 1 34 21 93 88 Fax: +33 1 30 37 31 85  AMP 7 rue des Meuniers -Z.A. 91520 Egly France Tel: +33 1 69 26 93 44 Fax: +33 1 69 26 92 85  Automatismes Sicli 1 rue Yvan Pavlov 93152 Le Blanc Mesnil Cedex France Tel: +33 1 49 39 40 00 Fax: +33 1 48 65 60 04	The listed companies are capable of receiving halons for recycling or providing recycled ones.

Country	Name and address	Remarks
France	Dehon Services	
(continued)	26 avenue du Petit Parc	
	94683 Vincennes Cedex	
	France	
	Tel: +33 1 43 98 75 00	
	Fax: +33 1 43 98 21 51	
	Desautel	
	Parc d'entreprises -BP 9	
	01121 Mont-Luel Cedex	
	France	
	Tel: +33 4 72 25 33 00	
	Fax: +33 4 72 25 33 39	
	Disse	
	Z.I. avenue Félix Louat	
	60300 Senlis	
	France	
	Tel: +33 3 44 60 95 10	
	Fax: +33 3 44 53 55 14	
	EFMT	
	4 rue Colbert	
	92700 Colombes	
	France	
	Tel: +33 1 47 86 83 00	
	Fax: +33 1 47 80 36 03	
	Cerberus Guinard	
	Z.I617 rue Fourmy-BP 20	
	78531 Buc Cedex, France	
	Tel: +33 1 30 84 66 00	
	Fax: +33 1 39 56 42 08	

Country	Name and address	Remarks
France (continued)	EMS 4 rue Jean Monnet - BP 606 95196 Goussanville France Tel: +33 1 39 88 63 55 Fax: +33 1 39 88 06 73  Kidde Dexareo 4 rue Henri Poincaré 92160 Anthony Cedex Tel: +33 1 46 66 08 08 Fax: +33 1 46 66 23 24  Sfeme Les Linards - BP 1250 03104 Montluçon Cedex France Tel: +33 4 70 08 12 00 Fax: +33 4 70 29 37 32	
Norway	Spesialavfallsstasjonen Bergen Interkommunale Renholdsverk (BIR) Fleslandsvn. 244 N-5068 Flesland, Norway Tel: +47 55 22 91 33 Fax: +47 55 99 14 32  N.SONTUN A/S Nedre Nøttveit 16, P.O. Box 124 N-5046 Rådal, Norway Tel: +47 55 13 00 94 Fax: +47 55 13 30 33	This is purely a reception facility and is not allowed to refill halon containers on board ships.  The companies listed below this point are accepted to store and refill halon containers on board ships. The halon capacity stored by these companies to refill halon containers on board ships would be between 1,000 kg and 15,000 kg.

Country	Name and address	Remarks
Norway (continued)	UNITOR P.O. Box 4 N-4033 Forus, Norway Tel: +47 51 57 01 33 Fax: +47 51 57 12 62  Maritime gmc as P.O. Box 4048 Tasta N-4004 Stavanger, Norway Tel: +47 51 84 80 00 Fax: +47 51 84 80 89  NOHA Brannteknikk AS Avd. Trondheim, P.O. Box 762 N-7075 Tiller, Norway Tel: +47 72 88 84 77 Fax: +47 72 88 51 65	
Peru		The Government of Peru has decided not to establish halon banking facilities.
Republic of Korea	Hanju Chemical Co., Ltd. 326-79 Songjeong-Ri, Mado-Myeon, Hwaseong-Gun, Kyeonggi-Do, Republic of Korea Tel: +82-339-782-9591/9592/9593 Fax: +82-337-782-9595	Facilities for Halon 1301 and Halon 1211:           Capacity         Number         Total           (tons)         (tons)           Fixed tank         15         2         30           36         1         36           Portable cylinder         1         50         50

Country	Name and address	Remarks
Russian Federation	Company "Ozone" St. Petersburg 198330 P.O. Box 37 Tel/Fax: (812) 325 1373	The company offers the following services:  .1 halons 2402 and 1301 recovery, charging and recharging of fire-extinguishing systems;  .2 supply of reclaimed halons 2402, 1301 in any containers;  .3 disposal of unsuitable halons; and  .4 analytical control of halons quality.  Currently the company grants availability of reclaimed halon 2402 in amount of 10 MT and reclaimed halon 1301 in amount of 4 MT.
United States	Halon Recycling Corporation 2111 Wilson Boulevard, 8th Floor Arlington, Virginia 22201 United States of America Tel: +1 800 258 1283 Fax: +1 703 243 2874 E-mail: harc96@aol.com	The Halon Recycling Corporation (HRC) acts as the contact point both nationally and internationally for the Unite States halon recycling and banking and also serves as the focal point for industry and government interaction on halon recycling issues. Further information can be obtained from the HRC website at www.halon.org.
Vanuatu		The Government of Vanuatu has decided not to establish halon banking facilities.